



Assessment Results Exceedance Tables

Of the 98 samples collected at Coman Hill Elementary School, 10 (10.20%) indicated lead concentrations above 15 ppb. The table below details the sample locations for each of these samples and their concentrations.

Coman Hill Elementary School		
Date	Location	Lead Level (ppb)
09/17/16	Sink Rm 109	29.7
09/17/16	Sink Rm 6	16.1
09/17/16	Sink Rm 7	21.6
09/17/16	Sink Rm 19	16.5
09/17/16	Sink Rm 18	16.5
09/17/16	Sink Rm 15	92.3
09/17/16	Back Left Hand Prep Sink	19.9
09/17/16	Teacher Sink Inside Rm 29	21.4
09/17/16	Right Hand Back Wall Rm 29	16.4
09/17/16	Teachers Faucet Rm 30	47.5

Of the 105 samples collected at Wampus Elementary School, 31 (29.52%) indicated lead concentrations above 15 ppb. Of these 31 samples with elevated lead concentrations, 14 were sampled from locations not used for consumption, no access or auto mix tempered faucets. The table below details the sample locations for the remaining 17 samples and their respective concentrations.

Wampus Elementary School		
Date	Location	Lead Level (ppb)
09/17/16	LAB Sink	167
09/17/16	Rm 9 Fountain	37.1
09/17/16	Rm 9 Sink	18.8
09/17/16	Rm 10 Fountain	26.9
09/17/16	Rm 10 Sink	54.1
09/17/16	Rm 11 Fountain	19.5
09/17/16	Rm 11 Sink	29.2
09/17/16	Work rm 18 sink	17.1
09/17/16	Rm 12 Sink (Fountain not working)	30.5
09/17/16	Rm 13 Sink	41.4

Wampus Elementary School		
Date	Location	Lead Level (ppb)
09/17/16	Rm 14 Fountain	17.8
09/17/16	Rm 14 Sink	15.1
09/17/16	Rm 15 Fountain	26.1
09/17/16	Rm 43 Sink right side	46.7
09/17/16	Rm 42 Fountain	32.3
09/17/16	Rm 41 Sink Left	43.2
09/17/16	Stage 1 Fountain	34.1



Assessment Results Exceedance Table

Of the 120 samples collected at Crittenden Middle School, 53 (44.2%) had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Crittenden Middle School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/15/16	HCMS-06	1 st	Sink in Room 145	54.0
10/15/16	HCMS-10	1 st	Sink in District Sp. Ed. Kitchenette	18.3
10/15/16	HCMS-11	1 st	Sink in Room 143 Teacher's Desk	17.8
10/15/16	HCMS-16	1 st	Sink in Room 142 Teacher's Desk	26.1
10/15/16	HCMS-20	1 st	Sink in Girls Locker Room 119	72.0
10/15/16	HCMS-29	1 st	Sink in Room 105	17.2
10/15/16	HCMS-32	1 st	Sink in Room 109 (2nd from Left)	22.7
10/15/16	HCMS-33	1 st	Sink in Room 109 (Third from Left)	16.1
10/15/16	HCMS-34	1 st	Sink in Room 109 (Fourth from Left)	16.2
10/15/16	HCMS-40	1 st	Sink in Room 109 (Tenth from Left)	15.6
10/15/16	HCMS-42	1 st	Sink in Room 109 (Twelfth from Left)	15.8
10/15/16	HCMS-44	1 st	Sink in Room 109 (Fourteenth from Left)	19.5
10/15/16	HCMS-54	1 st	Sink in Room 102 (Ninth from Left)	21.4
10/15/16	HCMS-55	1 st	Sink in Room 102 (Tenth from Left)	19.6
10/15/16	HCMS-56	1 st	Sink in Room 102 (Eleventh from Left)	17.6
10/15/16	HCMS-58	1 st	Sink in Room 102 (Thirteenth from Left)	19.2
10/15/16	HCMS-59	1 st	Sink in Room 102 (Fourteenth from Left)	28.8
10/15/16	HCMS-60	1 st	Sink Between Rooms 102 & 103	23.6
10/15/16	HCMS-61	1 st	Sink in Room 108 (First from Left)	23.9
10/15/16	HCMS-62	1 st	Sink in Room 108 (Second from Left)	44.0
10/15/16	HCMS-63	1 st	Sink in Room 108 (Third from Left)	17.6
10/15/16	HCMS-65	1 st	Sink in Room 108 (Fifth from Left)	17.5
10/15/16	HCMS-66	1 st	Sink in Room 108 (Sixth from Left)	18.3
10/15/16	HCMS-68	1 st	Sink in Room 108 (Eighth from Left)	17.8
10/15/16	HCMS-69	1 st	Sink in Room 108 (Ninth from Left)	19.2
10/15/16	HCMS-70	1 st	Sink in Room 108 (Tenth from Left)	15.8
10/15/16	HCMS-71	1 st	Sink in Room 108 (Eleventh from Left)	21.0
10/15/16	HCMS-72	1 st	Sink in Room 108 (Twelfth from Left)	17.3
10/15/16	HCMS-73	1 st	Sink in Room 108 (Thirteenth from Left)	17.8
10/15/16	HCMS-74	1 st	Sink in Room 108 (Fourteenth from Left)	18.9
10/15/16	HCMS-76	1 st	Sink in Room 103 (Second from Left)	19.1
10/15/16	HCMS-77	1 st	Sink in Room 103 (Third from Left)	18.2

Crittenden Middle School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/15/16	HCMS-78	1 st	Sink in Room 103 (Fourth from Left)	22.7
10/15/16	HCMS-80	1 st	Sink in Room 103 (Sixth from Left)	23.3
10/15/16	HCMS-82	1 st	Sink in Room 103 (Eighth from Left)	21.1
10/15/16	HCMS-86	1 st	Sink in Room 103 (Twelfth from Left)	17.5
10/15/16	HCMS-87	1 st	Sink in Room 103 (Thirteenth from Left)	16.8
10/15/16	HCMS-90	1 st	Sink in Room 107 (First from Left)	51.8
10/15/16	HCMS-	1 st	Sink in Room 107 (Second from Left)	36.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Third from Left)	26.3
10/15/16	HCMS-	1 st	Sink in Room 107 (Fourth from Left)	42.5
10/15/16	HCMS-	1 st	Sink in Room 107 (Fifth from Left)	26.5
10/15/16	HCMS-	1 st	Sink in Room 107 (Sixth from Left)	47.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Seventh from Left)	26.3
10/15/16	HCMS-	1 st	Sink in Room 107 (Eighth from Left)	30.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Ninth from Left)	32.9
10/15/16	HCMS-	1 st	Sink in Room 107 (Tenth from Left)	59.6
10/15/16	HCMS-	1 st	Sink in Room 107 (Eleventh from Left)	21.5
10/15/16	HCMS-	1 st	Sink in Room 107 (Twelfth from Left)	28.9
10/15/16	HCMS-	1 st	Sink in Room 107 (Thirteenth from Left)	19.1
10/15/16	HCMS-	1 st	Sink in Room 107 (Fourteenth from Left)	32.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Fifteenth from Left)	29.0
10/15/16	HCMS-	1 st	Sink in Room 150 – Right by Closet	15.6

Of the 170 samples collected at Byram Hills High School, 45 (26.5%) had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Byram Hills High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/15/16	BHHS-24	1 st	Sink in Kitchen prep; pot filler (Right)	33.4
10/15/16	BHHS-39	1 st	Sink in Room 111 (1)	403
10/15/16	BHHS-40	1 st	Sink in Room 111 (2)	794
10/15/16	BHHS-41	1 st	Sink in Room 111 (3)	26.4
10/15/16	BHHS-42	1 st	Sink in Room 111 (4)	629
10/15/16	BHHS-43	1 st	Sink in Room 111 (5)	33.8
10/15/16	BHHS-44	1 st	Sink in Room 111 Teacher Chem Storage	160
10/15/16	BHHS-45	1 st	Sink in Room 112A	87.8
10/15/16	BHHS-46	1 st	Sink in Room 112 (1)	15.4
10/15/16	BHHS-47	1 st	Sink in Room 112 (2)	18.3
10/15/16	BHHS-49	1 st	Sink in Room 112 (4)	17.2

Byram Hills High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/15/16	BHHS-50	1 st	Sink in Room 112 (5)	16.6
10/15/16	BHHS-52	1 st	Sink in Room 109 Kitchen Sink	289
10/15/16	BHHS-57	1 st	Sink in Science Office Kitchen Room 208	28.9
10/15/16	BHHS-60	1 st	Sink in Room 209 (3)	18.3
10/15/16	BHHS-61	1 st	Sink in Room 209 (4)	25.0
10/15/16	BHHS-62	1 st	Sink in Room 209 (6)	329
10/15/16	BHHS-63	1 st	Sink in Room 210 (1)	17.6
10/15/16	BHHS-65	1 st	Sink in Room 210 (3)	15.0
10/15/16	BHHS-67	1 st	Sink in Room 210 (5)	27.3
10/15/16	BHHS-68	1 st	Sink in Room 211 (1)	70.5
10/15/16	BHHS-69	1 st	Sink in Room 211 (2)	22.7
10/15/16	BHHS-70	1 st	Sink in Room 211 (3)	35.2
10/15/16	BHHS-73	1 st	Sink in Room 211 (6)	19.0
10/15/16	BHHS-78	1 st	Sink in Storage Room 310A (Left)	28.1
10/15/16	BHHS-79	1 st	Sink in Storage Room 310A (Right)	25.4
10/15/16	BHHS-111	1 st	Sink in Room 313/311 Prep Room (Left)	44.8
10/15/16	BHHS-113	1 st	Ice machine in Room 313/311	1120
10/15/16	BHHS-120	1 st	Sink in Room 311 Wash Sink 4	16.2
10/15/16	BHHS-130	1 st	Sink in Room 309 2 Fume Hood	26.0
10/15/16	BHHS-143	1 st	Sink in Room 309 Wash Sink	56.1
10/15/16	BHHS-144	1 st	Sink in Prep Room 309/307 (Left)	326
10/15/16	BHHS-145	1 st	Sink in Prep Room 309/307 (Right)	110
10/15/16	BHHS-146	1 st	Sink in Room 307 (1, Left)	27.1
10/15/16	BHHS-147	1 st	Sink in Room 307 (1, Right)	73.5
10/15/16	BHHS-148	1 st	Sink in Room 307 (2, Left)	213
10/15/16	BHHS-149	1 st	Sink in Room 307 (2, Right)	904
10/15/16	BHHS-150	1 st	Sink in Room 307 (3, Left)	30.2
10/15/16	BHHS-151	1 st	Sink in Room 307 (3, Right)	15.5
10/15/16	BHHS-152	1 st	Sink in Room 307 (4, Wash Sink)	28.5
10/15/16	BHHS-154	1 st	Sink in Room 307 (5, Right)	16.8
10/15/16	BHHS-155	1 st	Sink in Room 307 (6, Left)	23.5
10/15/16	BHHS-156	1 st	Sink in Room 307 (6, Right)	31.7
10/15/16	BHHS-157	1 st	Sink in Room 307 (7, Left)	16.5
10/15/16	BHHS-159	1 st	Sink in Room 307 (8, Fume Hood)	48.7



Assessment Results Exceedance Table

Of the 120 samples collected at Crittenden Middle School, 53 (44.2%) had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Crittenden Middle School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/15/16	HCMS-06	1 st	Sink in Room 145	54.0
10/15/16	HCMS-10	1 st	Sink in District Sp. Ed. Kitchenette	18.3
10/15/16	HCMS-11	1 st	Sink in Room 143 Teacher's Desk	17.8
10/15/16	HCMS-16	1 st	Sink in Room 142 Teacher's Desk	26.1
10/15/16	HCMS-20	1 st	Sink in Girls Locker Room 119	72.0
10/15/16	HCMS-29	1 st	Sink in Room 105	17.2
10/15/16	HCMS-32	1 st	Sink in Room 109 (2nd from Left)	22.7
10/15/16	HCMS-33	1 st	Sink in Room 109 (Third from Left)	16.1
10/15/16	HCMS-34	1 st	Sink in Room 109 (Fourth from Left)	16.2
10/15/16	HCMS-40	1 st	Sink in Room 109 (Tenth from Left)	15.6
10/15/16	HCMS-42	1 st	Sink in Room 109 (Twelfth from Left)	15.8
10/15/16	HCMS-44	1 st	Sink in Room 109 (Fourteenth from Left)	19.5
10/15/16	HCMS-54	1 st	Sink in Room 102 (Ninth from Left)	21.4
10/15/16	HCMS-55	1 st	Sink in Room 102 (Tenth from Left)	19.6
10/15/16	HCMS-56	1 st	Sink in Room 102 (Eleventh from Left)	17.6
10/15/16	HCMS-58	1 st	Sink in Room 102 (Thirteenth from Left)	19.2
10/15/16	HCMS-59	1 st	Sink in Room 102 (Fourteenth from Left)	28.8
10/15/16	HCMS-60	1 st	Sink Between Rooms 102 & 103	23.6
10/15/16	HCMS-61	1 st	Sink in Room 108 (First from Left)	23.9
10/15/16	HCMS-62	1 st	Sink in Room 108 (Second from Left)	44.0
10/15/16	HCMS-63	1 st	Sink in Room 108 (Third from Left)	17.6
10/15/16	HCMS-65	1 st	Sink in Room 108 (Fifth from Left)	17.5
10/15/16	HCMS-66	1 st	Sink in Room 108 (Sixth from Left)	18.3
10/15/16	HCMS-68	1 st	Sink in Room 108 (Eighth from Left)	17.8
10/15/16	HCMS-69	1 st	Sink in Room 108 (Ninth from Left)	19.2
10/15/16	HCMS-70	1 st	Sink in Room 108 (Tenth from Left)	15.8
10/15/16	HCMS-71	1 st	Sink in Room 108 (Eleventh from Left)	21.0
10/15/16	HCMS-72	1 st	Sink in Room 108 (Twelfth from Left)	17.3
10/15/16	HCMS-73	1 st	Sink in Room 108 (Thirteenth from Left)	17.8
10/15/16	HCMS-74	1 st	Sink in Room 108 (Fourteenth from Left)	18.9
10/15/16	HCMS-76	1 st	Sink in Room 103 (Second from Left)	19.1
10/15/16	HCMS-77	1 st	Sink in Room 103 (Third from Left)	18.2

10/15/16	HCMS-78	1 st	Sink in Room 103 (Fourth from Left)	22.7
10/15/16	HCMS-80	1 st	Sink in Room 103 (Sixth from Left)	23.3
10/15/16	HCMS-82	1 st	Sink in Room 103 (Eighth from Left)	21.1
10/15/16	HCMS-86	1 st	Sink in Room 103 (Twelfth from Left)	17.5
10/15/16	HCMS-87	1 st	Sink in Room 103 (Thirteenth from Left)	16.8
10/15/16	HCMS-90	1 st	Sink in Room 107 (First from Left)	51.8
10/15/16	HCMS-	1 st	Sink in Room 107 (Second from Left)	36.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Third from Left)	26.3
10/15/16	HCMS-	1 st	Sink in Room 107 (Fourth from Left)	42.5
10/15/16	HCMS-	1 st	Sink in Room 107 (Fifth from Left)	26.5
10/15/16	HCMS-	1 st	Sink in Room 107 (Sixth from Left)	47.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Seventh from Left)	26.3
10/15/16	HCMS-	1 st	Sink in Room 107 (Eighth from Left)	30.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Ninth from Left)	32.9
10/15/16	HCMS-	1 st	Sink in Room 107 (Tenth from Left)	59.6
10/15/16	HCMS-	1 st	Sink in Room 107 (Eleventh from Left)	21.5
10/15/16	HCMS-	1 st	Sink in Room 107 (Twelfth from Left)	28.9
10/15/16	HCMS-	1 st	Sink in Room 107 (Thirteenth from Left)	19.1
10/15/16	HCMS-	1 st	Sink in Room 107 (Fourteenth from Left)	32.7
10/15/16	HCMS-	1 st	Sink in Room 107 (Fifteenth from Left)	29.0
10/15/16	HCMS-	1 st	Sink in Room 150 – Right by Closet	15.6

Of the 170 samples collected at Byram Hills High School, 45 (26.5%) had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Byram Hills High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/15/16	BHHS-24	1 st	Sink in Kitchen prep; pot filler (Right)	33.4
10/15/16	BHHS-39	1 st	Sink in Room 111 (1)	403
10/15/16	BHHS-40	1 st	Sink in Room 111 (2)	794
10/15/16	BHHS-41	1 st	Sink in Room 111 (3)	26.4
10/15/16	BHHS-42	1 st	Sink in Room 111 (4)	629
10/15/16	BHHS-43	1 st	Sink in Room 111 (5)	33.8
10/15/16	BHHS-44	1 st	Sink in Room 111 Teacher Chem Storage	160
10/15/16	BHHS-45	1 st	Sink in Room 112A	87.8
10/15/16	BHHS-46	1 st	Sink in Room 112 (1)	15.4
10/15/16	BHHS-47	1 st	Sink in Room 112 (2)	18.3
10/15/16	BHHS-49	1 st	Sink in Room 112 (4)	17.2
10/15/16	BHHS-50	1 st	Sink in Room 112 (5)	16.6
10/15/16	BHHS-52	1 st	Sink in Room 109 Kitchen Sink	289

10/15/16	BHHS-57	1"	Sink in Science Office Kitchen Room 208	28.9
10/15/16	BHHS-60	1"	Sink in Room 209 (3)	18.3
10/15/16	BHHS-61	1"	Sink in Room 209 (4)	25.0
10/15/16	BHHS-62	1"	Sink in Room 209 (6)	329
10/15/16	BHHS-63	1"	Sink in Room 210 (1)	17.6
10/15/16	BHHS-65	1"	Sink in Room 210 (3)	15.0
10/15/16	BHHS-67	1"	Sink in Room 210 (5)	27.3
10/15/16	BHHS-68	1"	Sink in Room 211 (1)	70.5
10/15/16	BHHS-69	1"	Sink in Room 211 (2)	22.7
10/15/16	BHHS-70	1"	Sink in Room 211 (3)	35.2
10/15/16	BHHS-73	1"	Sink in Room 211 (6)	19.0
10/15/16	BHHS-78	1"	Sink in Storage Room 310A (Left)	28.1
10/15/16	BHHS-79	1"	Sink in Storage Room 310A (Right)	25.4
10/15/16	BHHS-111	1"	Sink in Room 313/311 Prep Room (Left)	44.8
10/15/16	BHHS-113	1"	Ice machine in Room 313/311	1120
10/15/16	BHHS-120	1"	Sink in Room 311 Wash Sink 4	16.2
10/15/16	BHHS-130	1"	Sink in Room 309 2 Fume Hood	26.0
10/15/16	BHHS-143	1"	Sink in Room 309 Wash Sink	56.1
10/15/16	BHHS-144	1"	Sink in Prep Room 309/307 (Left)	326
10/15/16	BHHS-145	1"	Sink in Prep Room 309/307 (Right)	110
10/15/16	BHHS-146	1"	Sink in Room 307 (1, Left)	27.1
10/15/16	BHHS-147	1"	Sink in Room 307 (1, Right)	73.5
10/15/16	BHHS-148	1"	Sink in Room 307 (2, Left)	213
10/15/16	BHHS-149	1"	Sink in Room 307 (2, Right)	904
10/15/16	BHHS-150	1"	Sink in Room 307 (3, Left)	30.2
10/15/16	BHHS-151	1"	Sink in Room 307 (3, Right)	15.5
10/15/16	BHHS-152	1"	Sink in Room 307 (4, Wash Sink)	28.5
10/15/16	BHHS-154	1"	Sink in Room 307 (5, Right)	16.8
10/15/16	BHHS-155	1"	Sink in Room 307 (6, Left)	23.5
10/15/16	BHHS-156	1"	Sink in Room 307 (6, Right)	31.7
10/15/16	BHHS-157	1"	Sink in Room 307 (7, Left)	16.5
10/15/16	BHHS-159	1"	Sink in Room 307 (8, Fume Hood)	48.7